

1st qtr inspection 2000

0002

Sample file
ACT/015/002
Incoming

POND INSPECTION REPORT

POND: Sediment

LOCATION: J.B. King Mine

| <u>ITEM</u> | <u>REMARKS</u> |
|--|--------------------|
| (1) Potential Safety Hazards | <u>None</u> |
| (2) Slope Stability | <u>Good</u> |
| (3) Erosion | <u>very little</u> |
| (4) Construction and Maintenance Performance Standards | <u>Good</u> |
| (5) Recommendations/Comments | <u>pond dry</u> |

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

RECEIVED

FEB 02 2000

DIVISION OF
OIL, GAS AND MINING

Jim Blackburn
1/31/00 Date